Pointe Scientific, Inc.

Instrument Application

Analyzer: Hitachi 902

Test: Albumin

No 1. Test Name	ALBG
No 2. Assay Code (Mthd)	1 Point
No 3. Assay Code (2.Test)	0
No 4. Reaction Time	3
No 5. Assay Point 1	5
No 6. Assay Point 2	0
No 7. Assay Point 3	0
No 8. Assay Point 4	0
No 9. Wavelength (SUB)	700
No 10. Wavelength (MAIN)	600
No 11. Sample Volume	3.0
No 12. R1 Volume	350
No 13. R1 Position	0*
No 14. R1 Bottle Size	Large
No 15. R2 Volume	0
No 16. R2 Position	0
No 17. R2 Bottle Size	Small
No 18. R3 Volume	0
No 19. R3 Position	0
No 20. R3 Bottle Size	Small
No 21. Calib. Type (Type)	Linear
No 22. Calib. Type (Wght)	0
No 23. Calib. Conc. 1	0.0
No 24. Calib. Pos. 1	36
No 25. Calib. Conc. 2	0*
No 26. Calib. Pos. 2	37
No 27. Calib. Conc. 3	0
No 28. Calib. Pos. 3	0
No 29. Calib. Conc. 4	0
No 30. Calib. Pos. 4	0
No 31. Calib. Conc. 5	0
No 32. Calib. Pos. 5	0
No 33. Calib. Conc. 6	0
No 34. Calib. Pos. 6	0
No 35. S1 ABS.	0
No 36. K Factor	10000
No 37. K2 Factor	10000
No 38. K3 Factor	10000
No 39. K4 Factor	10000
No 40. K5 Factor	10000
No 41. A Factor	0
No 42. B Factor	0
No 43. C Factor	0
No 44. SD Limit	0.1
No 45. Duplicate Limit	75
No 46. Sens. Limit	1000
No 47. S1ABS. Limit (L)	0
No 48. S1ABS. Limit (H)	4000
No 49. ABS Limit	0
No 49. ABS Limit	0
No 50. ABS Limit (D/I)	Increase
No 51. Prozone Limit	0
No 52. Proz Limit (Upp/Low)	Lower**
No 53. Prozone (End Point)	35
No 54. Expect. Value (L)	3.2
No 55. Expect. Value (H)	5.2
No 56. Instr. Factor (a)	1.0
No 57. Instr. Factor (b)	0.0
No 58. Key Setting	-*

It is recommended that two levels of control material be assayed daily. Reorder PSI Chemistry Controls Cat.# C7590-50 & C7591-50.

Rev. 1-03

Application 104

Pointe Scientific, Inc.

Instrument Application

Analyzer: Hitachi 902

Test: Alk. Phosphatase

No. 1. Test Name	Alk P
No 2. Assay Code (Mthd)	Rate A
No 3. Assay Code (2.Test)	0
No 4. Reaction Time	10
No 5. Assay Point 1	21
No 6. Assay Point 2	33
No 7. Assay Point 3	0
No 8. Assay Point 4	0
No 9. Wavelength (SUB)	700
No 10. Wavelength (MAIN)	415
No 11. Sample Volume	
No 12. R1 Volume	250
No 13. R1 Position	0*
No 14. R1 Bottle Size	Large
No 15. R2 Volume	0
No 16. R2 Position	0*
No 17. R2 Bottle Size	Small
No 18. R3 Volume	50
No 19. R3 Position	0*
No 20. R3 Bottle Size	Large
No 21. Calib. Type (Type)	K Factor
No 22. Calib. Type (Wght)	0
No 23. Calib. Conc.1	0
No 24. Calib. Pos.1	36
No 25. Calib. Conc.2	0
No 26. Calib. Pos.2	0
No 27. Calib. Conc.3	0
No 28. Calib. Pos.3	0
No 29. Calib. Conc.4	0
No 30. Calib. Pos.4	0
No 31. Calib. Conc.5	0
No 32. Calib. Pos. 5	0
No 33. Calib. Conc.6	0
No 34. Calib. Pos. 6	0
No 35. S1 ABS.	0
No 36. K Factor	0#
No 37. K2 Factor	10000
No 38. K3 Factor	10000
No 39. K4 Factor	10000
No 40. K5 Factor	10000
No 41. A Factor	0
No 42. B Factor	0
No 43. C Factor	0
No 44. SD Limit	0.1
No 45. Duplicate Limit	110
No 47. S1ABS. Limit (L)	0
No 48. S1ABS. Limit (H)	4000
No 49. ABS Limit	25000
No 50. ABS Limit (D/I)	Increase
No 51. Prozone Limit	0
No 52. Proz Limit (Upp/Low)	Lower**
No 53. Prozone (End Point)	35
No 54. Expect. Value (L)	35
No 55. Expect. Value (H)	123
No 56. Instr. Factor (a)	1.0
No 57. Instr. Factor (b)	0.0
No 58. Key Setting	-*

*User-defined

**Chemistry Parameters report will list D for lower or U for upper.

#K Factor is determined during installation

It is recommended that two levels of control material be assayed daily. Reorder PSI Chemistry Controls Cat.# C7590-50 & C7591-50.

Rev. 1-03

Application 104

No 46. Sens. Limit 1000

Pointe Scientific, Inc.

Instrument Application

Analyzer: Hitachi 902

Test: ALT

No. 1. Test Name	ALT
No 2. Assay Code (Mthd)	Rate A
No 3. Assay Code (2.Test)	0
No 4. Reaction Time	10
No 5. Assay Point 1	22
No 6. Assay Point 2	35
No 7. Assay Point 3	0
No 8. Assay Point 4	0
No 9. Wavelength (SUB)	700
No 10. Wavelength (MAIN)	340
No 11. Sample Volume	15.0
No 12. R1 Volume	250
No 13. R1 Position	0*
No 14. R1 Bottle Size	Large
No 15. R2 Volume	0
No 16. R2 Position	0
No 17. R2 Bottle Size	Large
No 18. R3 Volume	50
No 19. R3 Position	0*
No 20. R3 Bottle Size	Large
No 21. Calib. Type (Type)	K Factor
No 22. Calib. Type (Wght)	0
No 23. Calib. Conc.1	0
No 24. Calib. Pos.1	36
No 25. Calib. Conc.2	0
No 26. Calib. Pos.2	0
No 27. Calib. Conc.3	0
No 28. Calib. Pos. 3	0
No 29. Calib. Conc.4	0
No 30. Calib. Pos.4	0
No 31. Calib. Conc.5	0
No 32. Calib. Pos. 5	0
No 33. Calib. Conc.6	0
No 34. Calib. Pos. 6	0
No 35. S1 ABS.	0
No 36. K Factor	0#
No 37. K2 Factor	10000
No 38. K3 Factor	10000
No 39. K4 Factor	10000
No 40. K5 Factor	10000
No 41. A Factor	0
No 42. B Factor	0
No 43. C Factor	0
No 44. SD Limit	0.1
No 45. Duplicate Limit	20
No 47. S1ABS. Limit (L)	7500
No 48. S1ABS. Limit (H)	25000
No 49. ABS Limit	7000
No 50. ABS Limit (D/I)	Decrease
No 51. Prozone Limit	0
No 52. Proz Limit (Upp/Low)	Lower**
No 53. Prozone (End Point)	35
No 54. Expect. Value (L)	0
No 55. Expect. Value (H)	37
No 56. Instr. Factor (a)	1.0
No 57. Instr. Factor (b)	0.0
No 58. Key Setting	-*

*User-defined

**Chemistry Parameters report will list D for lower or U for upper.

#K Factor is determined during installation.

It is recommended that two levels of control material be assayed daily. Reorder PSI Chemistry Controls Cat.# C7590-50 & C7591-50.

Rev. 1-03

Application 106

No 46. Sens. Limit 0

Pointe Scientific, Inc.

Instrument Application

Analyzer: Hitachi 902

Test: Amylase

No. 1. Test Nam	AMYL
No 2. Assay Code (Mthd)	Rate A
No 3. Assay Code (2.Test)	0
No 4. Reaction Time	5
No 5. Assay Point 1	13
No 6. Assay Point 2	17
No 7. Assay Point 3	0
No 8. Assay Point 4	0
No 9. Wavelength (SUB)	700
No 10. Wavelength (MAIN)	415
No 11. Sample Volume	10.0
No 12. R1 Volume	250
No 13. R1 Position	0*
No 14. R1 Bottle Size	Large
No 15. R2 Volume	50
No 16. R2 Position	0*
No 17. R2 Bottle Size	Small
No 18. R3 Volume	0
No 19. R3 Position	0
No 20. R3 Bottle Size	Small
No 21. Calib. Type (Type)	K Factor
No 22. Calib. Type (Wght)	0
No 23. Calib. Conc.1	0
No 24. Calib. Pos.1	36*
No 25. Calib. Conc.2	0
No 26. Calib. Pos.2	0
No 27. Calib. Conc.3	0
No 28. Calib. Pos. 3	0
No 29. Calib. Conc.4	0
No 30. Calib. Pos.4	0
No 31. Calib. Conc.5	0
No 32. Calib. Pos. 5	0
No 33. Calib. Conc.6	0
No 34. Calib. Pos. 6	0
No 35. S1 ABS.	0
No 36. K Factor	0#
No 37. K2 Factor	10000
No 38. K3 Factor	10000
No 39. K4 Factor	10000
No 40. K5 Factor	10000
No 41. A Factor	0
No 42. B Factor	0
No 43. C Factor	0
No 44. SD Limit	0.1
No 45. Duplicate Limit	100
No 46. Sens. Limit	0
No 47. S1ABS. Limit (L)	-32000
No 48. S1ABS. Limit (H)	32000
No 49. ABS Limit	20000
No 50. ABS Limit (D/I)	Increase
No 51. Prozone Limit	0
No 52. Proz Limit (Upp/Low)	Lower**
No 53. Prozone (End Point)	35
No 54. Expect. Value (L)	25
No 55. Expect. Value (H)	125
No 56. Instr. Factor (a)	1.0
No 57. Instr. Factor (b)	0.0
No 58. Key Setting	-*

*User-defined

**Chemistry Parameters report will list D for lower or U for upper.

#K Factor is determined during installation.

It is recommended that two levels of control material be assayed daily. Reorder PSI Chemistry Controls Cat.# C7590-50 & C7591-50.

Rev. 1-03

Application 112

.

Pointe Scientific, Inc.

Instrument Application

Analyzer: Hitachi 902

Test: AST

No. 1. Test Name	AST
No 2. Assay Code (Mthd)	Rate A
No 3. Assay Code (2.Test)	0
No 4. Reaction Time	5
No 5. Assay Point 1	9
No 6. Assay Point 2	17
No 7. Assay Point 3	0
No 8. Assay Point 4	0
No 9. Wavelength (SUB)	700
No 10. Wavelength (MAIN)	340
No 11. Sample Volume	15.0
No 12. R1 Volume	250
No 13. R1 Position	0*
No 14. R1 Bottle Size	Large
No 15. R2 Volume	50
No 16. R2 Position	0*
No 17. R2 Bottle Size	Large
No 18. R3 Volume	0
No 19. R3 Position	0
No 20. R3 Bottle Size	Small
No 21. Calib. Type (Type)	K Factor
No 22. Calib. Type (Wght)	0
No 23. Calib. Conc.1	0
No 24. Calib. Pos.1	36
No 25. Calib. Conc.2	0*
No 26. Calib. Pos.2	0
No 27. Calib. Conc.3	0
No 28. Calib. Pos. 3	0
No 29. Calib. Conc.4	0
No 30. Calib. Pos.4	0
No 31. Calib. Conc.5	0
No 32. Calib. Pos. 5	0
No 33. Calib. Conc.6	0
No 34. Calib. Pos. 6	0
No 35. S1 ABS.	0
No 36. K Factor	0#
No 37. K2 Factor	10000
No 38. K3 Factor	10000
No 39. K4 Factor	10000
No 40. K5 Factor	10000
No 41. A Factor	0
No 42. B Factor	0
No 43. C Factor	0
No 44. SD Limit	0.1
No 45. Duplicate Limit	25
No 46. Sens. Limit	0
No 47. S1ABS. Limit (L)	8000
No 48. S1ABS. Limit (H)	25000
No 49. ABS Limit	5500
No 50. ABS Limit (D/I)	Decrease
No 51. Prozone Limit	0
No 52. Proz Limit (Upp/Low)	Lower**
No 53. Prozone (End Point)	35
No 54. Expect. Value (L)	5
No 55. Expect. Value (H)	34
No 56. Instr. Factor (a)	1.0
No 57. Instr. Factor (b)	0.0
No 58. Key Setting	-*

Application Code 114

*User-defined

**Chemistry Parameters report will list D for lower or U for upper.

#K Factor is determined during installation.

It is recommended that two levels of control material be assayed daily. Reorder PSI Chemistry Controls Cat.# C7590-50 & C7591-50.

Rev. 1-03

Application 117

Pointe Scientific, Inc.

Instrument Application

Analyzer: Hitachi 902

Test: auto HDL

No. 1. Test Name	HDL-C	No 47. S1ABS. Limit (L)	-32000
No 2. Assay Code (Mthd)	2 Point End	No 48. S1ABS. Limit (H)	32000
No 3. Assay Code (2.Test)	0	No 49. ABS Limit	0
No 4. Reaction Time	10	No 50. ABS Limit (D/I)	Increase
No 5. Assay Point 1	17	No 51. Prozone Limit	32000
No 6. Assay Point 2	35	No 52. Proz Limit (Upp/Low)	Upper***
No 7. Assay Point 3	0	No 53. Prozone (End Point)	35
No 8. Assay Point 4	0	No 54. Expect. Value (L)	30
No 9. Wavelength (SUB)	700	No 55. Expect. Value (H)	85
No 10. Wavelength (MAIN)	600	No 56. Instr. Factor (a)	1.0
No 11. Sample Volume	4.0	No 57. Instr. Factor (b)	0.0
No 12. R1 Volume	300	No 58. Key Setting	-*
No 13. R1 Position	0*		
No 14. R1 Bottle Size	Large		
No 15. R2 Volume	0		
No 16. R2 Position	0*		
No 17. R2 Bottle Size	Small		
No 18. R3 Volume	100		
No 19. R3 Position	0*		
No 20. R3 Bottle Size	Small		
No 21. Calib. Type (Type)	Linear		
No 22. Calib. Type (Wght)	0		
No 23. Calib. Conc.1	0		
No 24. Calib. Pos.1	36		
No 25. Calib. Conc.2	0**		
No 26. Calib. Pos.2	0*		
No 27. Calib. Conc.3	0		
No 28. Calib. Pos. 3	0		
No 29. Calib. Conc.4	0		
No 30. Calib. Pos.4	0		
No 31. Calib. Conc.5	0		
No 32. Calib. Pos. 5	0		
No 33. Calib. Conc.6	0		
No 34. Calib. Pos. 6	0		
No 35. S1 ABS.	0		
No 36. K Factor	10000		
No 37. K2 Factor	10000		
No 38. K3 Factor	10000		
No 39. K4 Factor	10000		
No 40. K5 Factor	10000		
No 41. A Factor	0		
No 42. B Factor	0		
No 43. C Factor	0		
No 44. SD Limit	0.1		
No 45. Duplicate Limit	80		
No 46. Sens. Limit	700		

*User-defined

***Chemistry Parameters report will list D for lower or U for upper.

**Enter the lot-specific value of the calibrator.

It is recommended that two levels of control material be assayed daily. Reorder PSI Chemistry Controls Cat.# C7590-50 & C7591-50.

Application Code 213

Pointe Scientific, Inc.

Instrument Application

Analyzer: Hitachi 902

Test: BUN

No. 1. Test Name	BUN	No 47. S1ABS. Limit (L)	-32000
No 2. Assay Code (Mthd)	2 Point Rate	No 48. S1ABS. Limit (H)	32000
No 3. Assay Code (2.Test)	0	No 49. ABS Limit	6500
No 4. Reaction Time	5	No 50. ABS Limit (D/I)	Decrease
No 5. Assay Point 1	10	No 51. Prozone Limit	0
No 6. Assay Point 2	15	No 52. Proz Limit (Upp/Low)	Lower**
No 7. Assay Point 3	0	No 53. Prozone (End Point)	35
No 8. Assay Point 4	0	No 54. Expect. Value (L)	7.0
No 9. Wavelength (SUB)	700	No 55. Expect. Value (H)	18.0
No 10. Wavelength (MAIN)	340	No 56. Instr. Factor (a)	1.0
No 11. Sample Volume	4.0	No 57. Instr. Factor (b)	0.0
No 12. R1 Volume	250	No 58. Key Setting	-*
No 13. R1 Position	0*		
No 14. R1 Bottle Size	Large		
No 15. R2 Volume	150		
No 16. R2 Position	0*		
No 17. R2 Bottle Size	Large		
No 18. R3 Volume	0		
No 19. R3 Position	0		
No 20. R3 Bottle Size	Large		
No 21. Calib. Type (Type)	Linear		
No 22. Calib. Type (Wght)	0		
No 23. Calib. Conc.1	0.0		
No 24. Calib. Pos.1	36		
No 25. Calib. Conc.2	0*		
No 26. Calib. Pos.2	37		
No 27. Calib. Conc.3	0		
No 28. Calib. Pos.	0		
No 29. Calib. Conc.4	0		
No 30. Calib. Pos.4	0		
No 31. Calib. Conc.5	0		
No 32. Calib. Pos. 5	0		
No 33. Calib. Conc.6	0		
No 34. Calib. Pos.	0		
No 35. S1 ABS.	0		
No 36. K Factor	10000		
No 37. K2 Factor	10000		
No 38. K3 Factor	10000		
No 39. K4 Factor	10000		
No 40. K5 Factor	10000		
No 41. A Factor	0		
No 42. B Factor	0		
No 43. C Factor	0		
No 44. SD Limit	0.1		
No 45. Duplicate Limit	60		
No 46. Sens. Limit	0		

*User-defined

**Chemistry Parameters report will list D for lower or U for upper.

It is recommended that two levels of control material be assayed daily. Reorder PSI Chemistry Controls Cat.# C7590-50 & C7591-50.

Rev. 1-03

Application Code 218

Pointe Scientific, Inc.

Instrument Application

Analyzer: Hitachi 902

Test: Calcium

No. 1. Test Name	CA
No 2. Assay Code (Mthd)	2 Point End
No 3. Assay Code (2.Test)	0
No 4. Reaction Time	5
No 5. Assay Point 1	5
No 6. Assay Point 2	17
No 7. Assay Point 3	0
No 8. Assay Point 4	0
No 9. Wavelength (SUB)	700
No 10. Wavelength (MAIN)	600
No 11. Sample Volume	10.0
No 12. R1 Volume	250
No 13. R1 Position	0*
No 14. R1 Bottle Size	Large
No 15. R2 Volume	100
No 16. R2 Position	0*
No 17. R2 Bottle Size	Large
No 18. R3 Volume	0
No 19. R3 Position	0
No 20. R3 Bottle Size	Large
No 21. Calib. Type (Type)	Linear
No 22. Calib. Type (Wght)	0
No 23. Calib. Conc.1	0.0
No 24. Calib. Pos.1	36
No 25. Calib. Conc.2	0*
No 26. Calib. Pos.2	37
No 27. Calib. Conc.3	0
No 28. Calib. Pos. 3	0
No 29. Calib. Conc.4	0
No 30. Calib. Pos.4	0
No 31. Calib. Conc.5	0
No 32. Calib. Pos. 5	0
No 33. Calib. Conc.6	0
No 34. Calib. Pos. 6	0
No 35. S1 ABS.	0
No 36. K Factor	10000
No 37. K2 Factor	10000
No 38. K3 Factor	10000
No 39. K4 Factor	10000
No 40. K5 Factor	10000
No 41. A Factor	0
No 42. B Factor	0
No 43. C Factor	0
No 44. SD Limit	0.1
No 45. Duplicate Limit	150
No 46. Sens. Limit	1200
No 47. S1ABS. Limit (L)	500
No 48. S1ABS. Limit (H)	4000
No 49. ABS Limit	0
No 50. ABS Limit (D/I)	Increase
No 51. Prozone Limit	32000
No 52. Proz Limit (Upp/Low)	Upper**
No 53. Prozone (End Point)	35
No 54. Expect. Value (L)	8.5
No 55. Expect. Value (H)	10.5
No 56. Instr. Factor (a)	1.0
No 57. Instr. Factor (b)	0.0
No 58. Key Setting	-*

*User-defined,

**Chemistry Parameters report will list D for lower or U for upper.

It is recommended that two levels of control material be assayed daily. Reorder PSI Chemistry Controls Cat.# C7590-50 & C7591-50.

Rev. 1-03

Application Code 129

Pointe Scientific, Inc.

Instrument Application

Analyzer: Hitachi 902

Test: Cholesterol

No. 1. Test Name	CHOL
No 2. Assay Code (Mthd)	1 Point
No 3. Assay Code (2.Test)	0
No 4. Reaction Time	5
No 5. Assay Point 1	17
No 6. Assay Point 2	0
No 7. Assay Point 3	0
No 8. Assay Point 4	0
No 9. Wavelength (SUB)	700
No 10. Wavelength (MAIN)	505
No 11. Sample Volume	3.0
No 12. R1 Volume	250
No 13. R1 Position	0*
No 14. R1 Bottle Size	Large
No 15. R2 Volume	0
No 16. R2 Position	0
No 17. R2 Bottle Size	Large
No 18. R3 Volume	0
No 19. R3 Position	0
No 20. R3 Bottle Size	Large
No 21. Calib. Type (Type)	Linear
No 22. Calib. Type (Wght)	0
No 23. Calib. Conc.1	0
No 24. Calib. Pos.1	36
No 25. Calib. Conc.2	0*
No 26. Calib. Pos.2	37
No 27. Calib. Conc.3	0
No 28. Calib. Pos.	0
No 29. Calib. Conc.4	0
No 30. Calib. Pos.4	0
No 31. Calib. Conc.5	0
No 32. Calib. Pos. 5	0
No 33. Calib. Conc.6	0
No 34. Calib. Pos.	0
No 35. S1 ABS.	0
No 36. K Factor	10000
No 37. K2 Factor	10000
No 38. K3 Factor	10000
No 39. K4 Factor	10000
No 40. K5 Factor	10000
No 41. A Factor	0
No 42. B Factor	0
No 43. C Factor	0
No 44. SD Limit	0.1
No 45. Duplicate Limit	220
No 46. Sens. Limit	2000
No 47. S1ABS. Limit (L)	0
No 48. S1ABS. Limit (H)	8000
No 49. ABS Limit	0
No 50. ABS Limit (D/I)	Increase
No 51. Prozone Limit	0
No 52. Proz Limit (Upp/Low)	Lower**
No 53. Prozone (End Point)	35
No 54. Expect. Value (L)	0
No 55. Expect. Value (H)	239
No 56. Instr. Factor (a)	1.0
No 57. Instr. Factor (b)	0.0
No 58. Key Setting -*	

*User-defined

**Chemistry Parameters report will list D for lower or U for upper.

It is recommended that two levels of control material be assayed daily. Reorder PSI Chemistry Controls Cat.# C7590-50 & C7591-50.

Application Code 132

Pointe Scientific, Inc.

Instrument Application

Analyzer: Hitachi 902

Test: CK

No. 1. Test Name	CK	No 47. S1ABS. Limit (L)	0
No 2. Assay Code (Mthd)	Rate A	No 48. S1ABS. Limit (H)	4000
No 3. Assay Code (2.Test)	0	No 49. ABS Limit	13000
No 4. Reaction Time	10	No 50. ABS Limit (D/I)	Increase
No 5. Assay Point 1	24	No 51. Prozone Limit	0
No 6. Assay Point 2	33	No 52. Proz Limit (Upp/Low)	Lower**
No 7. Assay Point 3	0	No 53. Prozone (End Point)	35
No 8. Assay Point 4	0	No 54. Expect. Value (L)	0
No 9. Wavelength (SUB)	376	No 55. Expect. Value (H)	160
No 10. Wavelength (MAIN)	340	No 56. Instr. Factor (a)	1.0
No 11. Sample Volume	7.0	No 57. Instr. Factor (b)	0.0
No 12. R1 Volume	250	No 58. Key Setting	-
No 13. R1 Position	0*		
No 14. R1 Bottle Size	Large		
No 15. R2 Volume	0		
No 16. R2 Position	0		
No 17. R2 Bottle Size	Small		
No 18. R3 Volume	50		
No 19. R3 Position	0		
No 20. R3 Bottle Size	Small		
No 21. Calib. Type (Type)	K Factor		
No 22. Calib. Type (Wght)	0		
No 23. Calib. Conc.1	0		
No 24. Calib. Pos.1	36		
No 25. Calib. Conc.2	0		
No 26. Calib. Pos.2	0		
No 27. Calib. Conc.3	0		
No 28. Calib. Pos. 3	0		
No 29. Calib. Conc.4	0		
No 30. Calib. Pos.4	0		
No 31. Calib. Conc.5	0		
No 32. Calib. Pos. 5	0		
No 33. Calib. Conc.6	0		
No 34. Calib. Pos.	0		
No 35. S1 ABS.	0		
No 36. K Factor	0#		
No 37. K2 Factor	10000		
No 38. K3 Factor	10000		
No 39. K4 Factor	10000		
No 40. K5 Factor	10000		
No 41. A Factor	0		
No 42. B Factor	0		
No 43. C Factor	0		
No 44. SD Limit	0.1		
No 45. Duplicate Limit	100		
No 46. Sens. Limit	0		

*User-defined

**Chemistry Parameters report will list D for lower or U for upper

#K Factor is determined during installation.

It is recommended that two levels of control material be assayed daily. Reorder PSI Chemistry Controls Cat.# C7590-50 & C7591-50.

Rev. 1-03

Application Code 134

,.

Pointe Scientific, Inc.

Instrument Application

Analyzer: Hitachi 902

Test: Carbon Dioxide

No. 1. Test Name	CO2
No 2. Assay Code (Mthd)	Rate A
No 3. Assay Code (2.Test)	0
No 4. Reaction Time	5
No 5. Assay Point 1	14
No 6. Assay Point 2	17
No 7. Assay Point 3	0
No 8. Assay Point 4	0
No 9. Wavelength (SUB)	700
No 10. Wavelength (MAIN)	340
No 11. Sample Volume	3.0
No 12. R1 Volume	300
No 13. R1 Position	0*
No 14. R1 Bottle Size	Large
No 15. R2 Volume	0
No 16. R2 Position	0
No 17. R2 Bottle Size	Small
No 18. R3 Volume	0
No 19. R3 Position	0
No 20. R3 Bottle Size	Small
No 21. Calib. Type (Type)	Linear
No 22. Calib. Type (Wght)	0
No 23. Calib. Conc.1	0
No 24. Calib. Pos.1	36
No 25. Calib. Conc.2	0*
No 26. Calib. Pos.2	37
No 27. Calib. Conc.3	0
No 28. Calib. Pos. 3	0
No 29. Calib. Conc.4	0
No 30. Calib. Pos.4	0
No 31. Calib. Conc.5	0
No 32. Calib. Pos. 5	0
No 33. Calib. Conc.6	0
No 34. Calib. Pos. 6	0
No 35. S1 ABS.	0
No 36. K Factor	10000
No 37. K2 Factor	10000
No 38. K3 Factor	10000
No 39. K4 Factor	10000
No 40. K5 Factor	10000
No 41. A Factor	0
No 42. B Factor	0
No 43. C Factor	0
No 44. SD Limit	0.1
No 45. Duplicate Limit	50
No 46. Sens. Limit	0
No 47. S1ABS. Limit (L)	8000
No 48. S1ABS. Limit (H)	30000
No 49. ABS Limit	0
No 50. ABS Limit (D/I)	Decrease
No 51. Prozone Limit	0
No 52. Proz Limit (Upp/Low)	Lower**
No 53. Prozone (End Point)	35
No 54. Expect. Value (L)	23.0
No 55. Expect. Value (H)	34.0
No 56. Instr. Factor (a)	1.0
No 57. Instr. Factor (b)	0.0
No 58. Key Setting	-*

*User-defined

**Chemistry Parameters report will list D for lower or U for upper.

It is recommended that two levels of control material be assayed daily. Reorder PSI Chemistry Controls Cat.# C7590-50 & C7591-50.

Rev. 1-03

Application Code *

Rev: 2/02

Pointe Scientific, Inc.

Instrument Application

Analyzer: Hitachi 902

Test: Creatinine

No 1.	Test Name	CREA	
No 2.	Assay Code (Mthd)	2 Point Rate	
No 3.	Assay Code (2.Test)	0	
No 4.	Reaction Time	4	
No 5.	Assay Point 1	9	
No 6.	Assay Point 2	13	
No 7.	Assay Point 3	0	
No 8.	Assay Point 4	0	
No 9.	Wavelength (SUB)	570	
No 10.	Wavelength (MAIN)	505	
No 11.	Sample Volume	15.0	
No 12.	R1 Volume	250	
No 13.	R1 Position	0*	
No 14.	R1 Bottle Size	Large	
No 15.	R2 Volume	50	
No 16.	R2 Position	0*	
No 17.	R2 Bottle Size	Large	
No 18.	R3 Volume	0	
No 19.	R3 Position	0	
No 20.	R3 Bottle Size	Small	
No 21.	Calib. Type (Type)	Linear	
No 22.	Calib. Type (Wght)	0	
No 23.	Calib. Conc. 1	0.0	
No 24.	Calib. Pos. 1	36	
No 25.	Calib. Conc. 2	0*	
No 26.	Calib. Pos. 2	37	
No 27.	Calib. Conc. 3	0	
No 28.	Calib. Pos. 3	0	
No 29.	Calib. Conc. 4	0	
No 30.	Calib. Pos. 4	0	
No 31.	Calib. Conc. 5	0	
No 32.	Calib. Pos. 5	0	
No 33.	Calib. Conc. 6	0	
No 34.	Calib. Pos. 6	0	
No 35.	S1 ABS.	0	
No 36.	K Factor	10000	
No 37.	K2 Factor	10000	
No 38.	K3 Factor	10000	
No 39.	K4 Factor	10000	
No 40.	K5 Factor	10000	
No 41.	A Factor	0	
No 42.	B Factor	0	
No 43.	C Factor	0	
No 44.	SD Limit	0.1	
No 45.	Duplicate Limit	10	
No 46.	Sens. Limit	100	
No 47.	S1ABS. Limit (L)	0	
No 48.	S1ABS. Limit (H)	4000	
No 49.	ABS Limit	5500	
No 50.	ABS Limit (D/I)	Increase	
No 51.	Prozone Limit	0	
No 52.	Proz Limit (Upp/Low)	Lower**	
No 53.	Prozone (End Point)	35	
No 54.	Expect. Value (L)	0.4	
No 55.	Expect. Value (H)	1.4	
No 56.	Instr. Factor (a)	1.0	
No 57.	Instr. Factor (b)	0.0	
No 58.	Key Setting	_*	

*User-defined

**Chemistry Parameters report will list D for lower or U for upper.

It is recommended that two levels of control material be assayed daily. Reorder PSI Chemistry Controls Cat.# C7590-50 & C7591-50.

Rev. 1-03

Application Code 140

Pointe Scientific, Inc.

Instrument Application

Analyzer: Hitachi 902

Test: GGT

No. 1. Test Name	GGT
No 2. Assay Code (Mthd)	Rate A
No 3. Assay Code (2.Test)	0
No 4. Reaction Time	10
No 5. Assay Point 1	21
No 6. Assay Point 2	33
No 7. Assay Point 3	0
No 8. Assay Point 4	0
No 9. Wavelength (SUB)	700
No 10. Wavelength (MAIN)	415
No 11. Sample Volume	7.0
No 12. R1 Volume	250
No 13. R1 Position	0*
No 14. R1 Bottle Size	Large
No 15. R2 Volume	0
No 16. R2 Position	0
No 17. R2 Bottle Size	Small
No 18. R3 Volume	100
No 19. R3 Position	0*
No 20. R3 Bottle Size	Large
No 21. Calib. Type (Type)	K Factor
No 22. Calib. Type (Wght)	0
No 23. Calib. Conc.1	0
No 24. Calib. Pos.1	36
No 25. Calib. Conc.2	0
No 26. Calib. Pos.2	0
No 27. Calib. Conc.3	0
No 28. Calib. Pos. 3	0
No 29. Calib. Conc.4	0
No 30. Calib. Pos.4	0
No 31. Calib. Conc.5	0
No 32. Calib. Pos. 5	0
No 33. Calib. Conc.6	0
No 34. Calib. Pos. 6	0
No 35. S1 ABS.	0
No 36. K Factor	0#
No 37. K2 Factor	10000
No 38. K3 Factor	10000
No 39. K4 Factor	10000
No 40. K5 Factor	10000
No 41. A Factor	0
No 42. B Factor	0
No 43. C Factor	0
No 44. SD Limit	0.1
No 45. Duplicate Limit	100
No 46. Sens. Limit	0
No 47. S1ABS. Limit (L)	0
No 48. S1ABS. Limit (H)	4000
No 49. ABS Limit	5500
No 50. ABS Limit (D/I)	Increase
No 51. Prozone Limit	0
No 52. Proz Limit (Upp/Low)	Lower**
No 53. Prozone (End Point)	35
No 54. Expect. Value (L)	8
No 55. Expect. Value (H)	54
No 56. Instr. Factor (a)	1.0
No 57. Instr. Factor (b)	0.0
No 58. Key Setting	-*

*User-defined

**Chemistry Parameters report will list D for lower or U for upper.

#K Factor is determined during installation.

It is recommended that two levels of control material be assayed daily. Reorder PSI Chemistry Controls Cat.# C7590-50 & C7591-50.

Rev. 1-03

Application Code 147

,

Pointe Scientific, Inc.

Instrument Application

Analyzer: Hitachi 902

Test: Glucose (Hex)

No. 1. Test Name	GLU	No 47. S1ABS. Limit (L)	-500
No 2. Assay Code (Mthd)	2 Point End	No 48. S1ABS. Limit (H)	2000
No 3. Assay Code (2.Test)	0	No 49. ABS Limit	0
No 4. Reaction Time	5	No 50. ABS Limit (D/I)	Increase
No 5. Assay Point 1	5	No 51. Prozone Limit	32000
No 6. Assay Point 2	17	No 52. Proz Limit (Upp/Low)	Upper**
No 7. Assay Point 3	0	No 53. Prozone (End Point)	35
No 8. Assay Point 4	0	No 54. Expect. Value (L)	65
No 9. Wavelength (SUB)	700	No 55. Expect. Value (H)	110
No 10. Wavelength (MAIN)	340	No 56. Instr. Factor (a)	1.0
No 11. Sample Volume	3.0	No 57. Instr. Factor (b)	0.0
No 12. R1 Volume	300	No 58. Key Setting	-*
No 13. R1 Position	0*		
No 14. R1 Bottle Size	Large		
No 15. R2 Volume	50		
No 16. R2 Position	0*		
No 17. R2 Bottle Size	Small		
No 18. R3 Volume	0		
No 19. R3 Position	0		
No 20. R3 Bottle Size	Small		
No 21. Calib. Type (Type)	Linear		
No 22. Calib. Type (Wght)	0		
No 23. Calib. Conc.1	0		
No 24. Calib. Pos.1	36		
No 25. Calib. Conc.2	0*		
No 26. Calib. Pos.2	37		
No 27. Calib. Conc.3	0		
No 28. Calib. Pos. 3	0		
No 29. Calib. Conc.4	0		
No 30. Calib. Pos.4	0		
No 31. Calib. Conc.5	0		
No 32. Calib. Pos. 5	0		
No 33. Calib. Conc.6	0		
No 34. Calib. Pos. 6	0		
No 35. S1 ABS.	0		
No 36. K Factor	10000		
No 37. K2 Factor	10000		
No 38. K3 Factor	10000		
No 39. K4 Factor	10000		
No 40. K5 Factor	10000		
No 41. A Factor	0		
No 42. B Factor	0		
No 43. C Factor	0		
No 44. SD Limit	0.1		
No 45. Duplicate Limit	250		
No 46. Sens. Limit	3000		

*User-defined

**Chemistry Parameters report will list D for lower or U for upper.

It is recommended that two levels of control material be assayed daily. Reorder PSI Chemistry Controls Cat.# C7590-50 & C7591-50.

Rev. 1-03

Application Code 148

Pointe Scientific, Inc.

Instrument Application

Analyzer: Hitachi 902
Test: HbA1c
Catalog #: H7541

No 1. Test Name	HbA1c	No 45. Duplicate Limit	200
No 2. Assay Code (Mthd)	1 Point End	No 46. Sens. Limit	700
No 3. Assay Code (2.Test)	0	No 47. S1ABS. Limit (L)	0
No 4. Reaction Time	10	No 48. S1ABS. Limit (H)	4000
No 5. Assay Point 1	35	No 49. ABS Limit	32000
No 6. Assay Point 2	0	No 50. ABS Limit (D/I)	Increase
No 7. Assay Point 3	0	No 51. Prozone Limit	0
No 8. Assay Point 4	0	No 52. Proz Limit (Upp/Low)	Lower**
No 9. Wavelength (SUB)	-	No 53. Prozone (End Point)	35
No 10. Wavelength (MAIN)	660	No 54. Expect. Value (L)	*
No 11. Sample Volume	5.0	No 55. Expect. Value (H)	*
No 12. R1 Volume	180	No 56. Instr. Factor (a)	1.0
No 13. R1 Position	0*	No 57. Instr. Factor (b)	0.0
No 14. R1 Bottle Size	Large	No 58. Key Setting	-*
No 15. R2 Volume	0		
No 16. R2 Position	0		
No 17. R2 Bottle Size	Small		
No 18. R3 Volume	60		
No 19. R3 Position	0*		
No 20. R3 Bottle Size	Small		
No 21. Calib. Type (Type)	Non Linear		
No 22. Calib. Type (Wght)	0		
No 23. Calib. Conc. 1	0.0		
No 24. Calib. Pos. 1	36		
No 25. Calib. Conc. 2	#		
No 26. Calib. Pos. 2	#		
No 27. Calib. Conc. 3	#		
No 28. Calib. Pos. 3	#		
No 29. Calib. Conc. 4	#		
No 30. Calib. Pos. 4	#		
No 31. Calib. Conc. 5	#		
No 32. Calib. Pos. 5	#		
No 33. Calib. Conc. 6	0		
No 34. Calib. Pos. 6	0		
No 35. S1 ABS.	0		
No 36. K Factor	10000		
No 37. K2 Factor	10000		
No 38. K3 Factor	10000		
No 39. K4 Factor	10000		
No 40. K5 Factor	10000		
No 41. A Factor	0		
No 42. B Factor	0		
No 43. C Factor	0		
No 44. SD Limit	0.1		

*User-defined,
**Chemistry Parameters report will list D for lower or U for upper
Enter concentration and Position of calibrators
It is recommended that two levels of control material be assayed daily.

Rev. 8-03 Non-validated application

Application Code: User Defined

Pointe Scientific, Inc.

Instrument Application

Analyzer: Hitachi 902

Test: LDH

No 1. Test Name	LD	No 46. Sens. Limit	0
No 2. Assay Code (Mthd)	Rate A	No 47. S1ABS. Limit (L)	1000
No 3. Assay Code (2.Test)	0	No 48. S1ABS. Limit (H)	6000
No 4. Reaction Time	10	No 49. ABS Limit	10000
No 5. Assay Point 1	24	No 50. ABS Limit (D/I)	Increase
No 6. Assay Point 2	31	No 51. Prozone Limit	0
No 7. Assay Point 3	0	No 52. Proz Limit (Upp/Low)	Lower**
No 8. Assay Point 4	0	No 53. Prozone (End Point)	35
No 9. Wavelength (SUB)	376	No 54. Expect. Value (L)	80
No 10. Wavelength (MAIN)	340	No 55. Expect. Value (H)	285
No 11. Sample Volume	9.0	No 56. Instr. Factor (a)	1.0
No 12. R1 Volume	250	No 57. Instr. Factor (b)	0.0
No 13. R1 Position	0*	No 58. Key Setting	_*
No 14. R1 Bottle Size	Large		
No 15. R2 Volume	0	*User-defined	
No 16. R2 Position	0	**Chemistry Parameters report will print D for lower or U for upper.	
No 17. R2 Bottle Size	Small	#K Factor is determined during installation	
No 18. R3 Volume	100		
No 19. R3 Position	0*		
No 20. R3 Bottle Size	Small	Rev. 1-03	
No 21. Calib. Type (Type)	K Factor		
No 22. Calib. Type (Wght)	0		
No 23. Calib. Conc. 1	0		
No 24. Calib. Pos. 1	36	Application Code 158	
No 25. Calib. Conc. 2	0		
No 26. Calib. Pos. 2	0		
No 27. Calib. Conc. 3	0		
No 28. Calib. Pos. 3	0		
No 29. Calib. Conc. 4	0		
No 30. Calib. Pos. 4	0		
No 31. Calib. Conc. 5	0		
No 32. Calib. Pos. 5	0		
No 33. Calib. Conc. 6	0		
No 34. Calib. Pos. 6	0		
No 35. S1 ABS.	0		
No 36. K Factor	0#		
No 37. K2 Factor	10000		
No 38. K3 Factor	10000		
No 39. K4 Factor	10000		
No 40. K5 Factor	10000		
No 41. A Factor	0		
No 42. B Factor	0		
No 43. C Factor	0		
No 44. SD Limit	0.1		
No 45. Duplicate Limit	100		

Pointe Scientific, Inc.

Instrument Application

Analyzer: Hitachi 902

Test: Magnesium

No. 1. Test Name	MG	No 47. S1ABS. Limit (L)	-5000
No 2. Assay Code (Mthd)	2 Point End	No 48. S1ABS. Limit (H)	4000
No 3. Assay Code (2.Test)	0	No 49. ABS Limit	0
No 4. Reaction Time	4	No 50. ABS Limit (D/I)	Increase
No 5. Assay Point 1	5	No 51. Prozone Limit	-32000
No 6. Assay Point 2	12	No 52. Proz Limit (Upp/Low)	Lower**
No 7. Assay Point 3	0	No 53. Prozone (End Point)	35
No 8. Assay Point 4	0	No 54. Expect. Value (L)	1.3
No 9. Wavelength (SUB)	700	No 55. Expect. Value (H)	2.1
No 10. Wavelength (MAIN)	546	No 56. Instr. Factor (a)	1.0
No 11. Sample Volume	4.0	No 57. Instr. Factor (b)	0.0
No 12. R1 Volume	240	No 58. Key Setting	-*
No 13. R1 Position	0*		
No 14. R1 Bottle Size	Large	*User-defined	
No 15. R2 Volume	240	**Chemistry Parameters report will list D for lower or U for upper.	
No 16. R2 Position	0*		
No 17. R2 Bottle Size	Large	It is recommended that two levels of control material be	
No 18. R3 Volume	0	assayed daily. Reorder PSI Chemistry Controls	
No 19. R3 Position	0	Cat.# C7590-50 & C7591-50.	
No 20. R3 Bottle Size	Large		
No 21. Calib. Type (Type)	Linear	Rev. 1-03	
No 22. Calib. Type (Wght)	0		
No 23. Calib. Conc.1	0.0		
No 24. Calib. Pos.1	36	Application Code 165	
No 25. Calib. Conc.2	0*		
No 26. Calib. Pos.2	37		
No 27. Calib. Conc.3	0		
No 28. Calib. Pos. 3	0		
No 29. Calib. Conc.4	0		
No 30. Calib. Pos.4	0		
No 31. Calib. Conc.5	0		
No 32. Calib. Pos. 5	0		
No 33. Calib. Conc.6	0		
No 34. Calib. Pos. 6	0		
No 35. S1 ABS.	0		
No 36. K Factor	10000		
No 37. K2 Factor	10000		
No 38. K3 Factor	10000		
No 39. K4 Factor	10000		
No 40. K5 Factor	10000		
No 41. A Factor	0		
No 42. B Factor	0		
No 43. C Factor	0		
No 44. SD Limit	0.1		
No 45. Duplicate Limit	250		
No 46. Sens. Limit	2000		

Pointe Scientific, Inc.

Instrument Application

Analyzer: Hitachi 902

Test: Phosphorus

No. 1. Test Name	Phos
No 2. Assay Code (Mthd)	2 Point End
No 3. Assay Code (2.Test)	0
No 4. Reaction Time	4
No 5. Assay Point 1	5
No 6. Assay Point 2	12
No 7. Assay Point 3	0
No 8. Assay Point 4	0
No 9. Wavelength (SUB)	700
No 10. Wavelength (MAIN)	340
No 11. Sample Volume	5.0
No 12. R1 Volume	250
No 13. R1 Position	0*
No 14. R1 Bottle Size	Large
No 15. R2 Volume	100
No 16. R2 Position	0
No 17. R2 Bottle Size	Large
No 18. R3 Volume	0
No 19. R3 Position	0
No 20. R3 Bottle Size	Large
No 21. Calib. Type (Type)	Linear
No 22. Calib. Type (Wght)	0
No 23. Calib. Conc.1	0.0
No 24. Calib. Pos.1	36
No 25. Calib. Conc.2	0*
No 26. Calib. Pos.2	37
No 27. Calib. Conc.3	0
No 28. Calib. Pos. 3	0
No 29. Calib. Conc.4	0
No 30. Calib. Pos.4	0
No 31. Calib. Conc.5	0
No 32. Calib. Pos. 5	0
No 33. Calib. Conc.6	0
No 34. Calib. Pos.	0
No 35. S1 ABS.	0
No 36. K Factor	10000
No 37. K2 Factor	10000
No 38. K3 Factor	10000
No 39. K4 Factor	10000
No 40. K5 Factor	10000
No 41. A Factor	0
No 42. B Factor	0
No 43. C Factor	0
No 44. SD Limit	0.1
No 45. Duplicate Limit	200
No 46. Sens. Limit	2000
No 47. S1ABS. Limit (L)	0
No 48. S1ABS. Limit (H)	7500
No 49. ABS Limit	0
No 50. ABS Limit (D/I)	Increase
No 51. Prozone Limit	-32000
No 52. Proz Limit (Upp/Low)	Lower**
No 53. Prozone (End Point)	35
No 54. Expect. Value (L)	2.5
No 55. Expect. Value (H)	4.8
No 56. Instr. Factor (a)	1.0
No 57. Instr. Factor (b)	0.0
No 58. Key Setting	-

*User-defined

**Chemistry Parameters report will list D for lower or U for upper.

#K Factor is determined during installation

It is recommended that two levels of control material be assayed daily. Reorder PSI Chemistry Controls Cat.# C7590-50 & C7591-50.

Rev. 1-03

Application Code 177

Pointe Scientific, Inc.

Instrument Application

Analyzer: Hitachi 902

Test: Rheumatoid Factor

No. 1. Test Name	RF
No 2. Assay Code (Mthd)	2 Point End
No 3. Assay Code (2.Test)	0
No 4. Reaction Time	10
No 5. Assay Point 1	17
No 6. Assay Point 2	35
No 7. Assay Point 3	0
No 8. Assay Point 4	0
No 9. Wavelength (SUB)	700
No 10. Wavelength (MAIN)	340
No 11. Sample Volume	12.0
No 12. R1 Volume	200
No 13. R1 Position	0*
No 14. R1 Bottle Size	Large
No 15. R2 Volume	0
No 16. R2 Position	0
No 17. R2 Bottle Size	Large
No 18. R3 Volume	60
No 19. R3 Position	0*
No 20. R3 Bottle Size	Large
No 21. Calib. Type (Type)	Spline
No 22. Calib. Type (Wght)	0
No 23. Calib. Conc.1	0.0*
No 24. Calib. Pos.1	36
No 25. Calib. Conc.2	0*
No 26. Calib. Pos.2	37
No 27. Calib. Conc.3	0
No 28. Calib. Pos. 3	0
No 29. Calib. Conc.4	0
No 30. Calib. Pos.4	0
No 31. Calib. Conc.5	0
No 32. Calib. Pos. 5	0
No 33. Calib. Conc.6	0
No 34. Calib. Pos. 6	0
No 35. S1 ABS.	0
No 36. K Factor	10000
No 37. K2 Factor	10000
No 38. K3 Factor	10000
No 39. K4 Factor	10000
No 40. K5 Factor	10000
No 41. A Factor	0
No 42. B Factor	0
No 43. C Factor	0
No 44. SD Limit	999
No 45. Duplicate Limit	500
No 46. Sens. Limit	0
No 47. S1ABS. Limit (L)	-32000
No 48. S1ABS. Limit (H)	32000
No 49. ABS Limit	0
No 50. ABS Limit (D/I)	Increase
No 51. Prozone Limit	-32000
No 52. Proz Limit (Upp/Low)	Lower**
No 53. Prozone (End Point)	35
No 54. Expect. Value (L)	2.5
No 55. Expect. Value (H)	4.8
No 56. Instr. Factor (a)	1.0
No 57. Instr. Factor (b)	0.0
No 58. Key Setting	-*

*User-defined,

**Chemistry Parameters report will list D for lower or U for upper.

#K factor is determined during installation.

.

Rev. 3-03

Pointe Scientific, Inc.

Instrument Application

Analyzer: Hitachi 902

Test: Total Protein

No. 1. Test Name	TP	No 47. S1ABS. Limit (L)	-4000
No 2. Assay Code (Mthd)	2 Point End	No 48. S1ABS. Limit (H)	0
No 3. Assay Code (2.Test)	0	No 49. ABS Limit	0
No 4. Reaction Time	10	No 50. ABS Limit (D/I)	Increase
No 5. Assay Point 1	5	No 51. Prozone Limit	0
No 6. Assay Point 2	5	No 52. Proz Limit (Upp/Low)	Lower**
No 7. Assay Point 3	35	No 53. Prozone (End Point)	35
No 8. Assay Point 4	0	No 54. Expect. Value (L)	6.2
No 9. Wavelength (SUB)	700	No 55. Expect. Value (H)	8.5
No 10. Wavelength (MAIN)	570	No 56. Instr. Factor (a)	1.0
No 11. Sample Volume	3.0	No 57. Instr. Factor (b)	0.0
No 12. R1 Volume	250	No 58. Key Setting	-*
No 13. R1 Position	0*		
No 14. R1 Bottle Size	Large	*User-defined	
No 15. R2 Volume	100	**Chemistry Parameters report will list D for lower or U for upper.	
No 16. R2 Position	0*		
No 17. R2 Bottle Size	Large	It is recommended that two levels of control material be	
No 18. R3 Volume	0	assayed daily. Reorder PSI Chemistry Controls	
No 19. R3 Position	0	Cat.# C7590-50 & C7591-50.	
No 20. R3 Bottle Size	Small		
No 21. Calib. Type (Type)	Linear	Rev. 1-03	
No 22. Calib. Type (Wght)	0		
No 23. Calib. Conc.1	0		
No 24. Calib. Pos.1	36	Application Code 189	
No 25. Calib. Conc.2	0*		
No 26. Calib. Pos.2	37		
No 27. Calib. Conc.3	0		
No 28. Calib. Pos.	0		
No 29. Calib. Conc.4	0		
No 30. Calib. Pos.4	0		
No 31. Calib. Conc.5	0		
No 32. Calib. Pos. 5	0		
No 33. Calib. Conc.6	0		
No 34. Calib. Pos.	0		
No 35. S1 ABS.	0		
No 36. K Factor	10000		
No 37. K2 Factor	10000		
No 38. K3 Factor	10000		
No 39. K4 Factor	10000		
No 40. K5 Factor	10000		
No 41. A Factor	0		
No 42. B Factor	0		
No 43. C Factor	0		
No 44. SD Limit	0.1		
No 45. Duplicate Limit	100		
No 46. Sens. Limit	1000		

Pointe Scientific, Inc.

Instrument Application

Analyzer: Hitachi 902

Test: Triglyceride

No. 1. Test Name	TRIG
No 2. Assay Code (Mthd)	1 Point
No 3. Assay Code (2.Test)	0
No 4. Reaction Time	10
No 5. Assay Point 1	35
No 6. Assay Point 2	0
No 7. Assay Point 3	0
No 8. Assay Point 4	0
No 9. Wavelength (SUB)	700
No 10. Wavelength (MAIN)	505
No 11. Sample Volume	3.0
No 12. R1 Volume	250
No 13. R1 Position	0*
No 14. R1 Bottle Size	Large
No 15. R2 Volume	0
No 16. R2 Position	0
No 17. R2 Bottle Size	Small
No 18. R3 Volume	0
No 19. R3 Position	0
No 20. R3 Bottle Size	Large
No 21. Calib. Type (Type)	Linear
No 22. Calib. Type (Wght)	0
No 23. Calib. Conc.1	0
No 24. Calib. Pos.1	36
No 25. Calib. Conc.2	0*
No 26. Calib. Pos.2	37
No 27. Calib. Conc.3	0
No 28. Calib. Pos. 3	0
No 29. Calib. Conc.4	0
No 30. Calib. Pos.4	0
No 31. Calib. Conc.5	0
No 32. Calib. Pos. 5	0
No 33. Calib. Conc.6	0
No 34. Calib. Pos. 6	0
No 35. S1 ABS.	0
No 36. K Factor	10000
No 37. K2 Factor	10000
No 38. K3 Factor	10000
No 39. K4 Factor	10000
No 40. K5 Factor	10000
No 41. A Factor	0
No 42. B Factor	0
No 43. C Factor	0
No 44. SD Limit	0.1
No 45. Duplicate Limit	200
No 46. Sens. Limit	1300
No 47. S1ABS. Limit (L)	0
No 48. S1ABS. Limit (H)	4000
No 49. ABS Limit	0
No 50. ABS Limit (D/I)	Increase
No 51. Prozone Limit	0
No 52. Proz Limit (Upp/Low)	Lower**
No 53. Prozone (End Point)	35
No 54. Expect. Value (L)	44
No 55. Expect. Value (H)	148
No 56. Instr. Factor (a)	1.0
No 57. Instr. Factor (b)	0.0
No 58. Key Setting	-*

*User-defined,

**Chemistry Parameters report will list D for lower or U for upper.

It is recommended that two levels of control material be assayed daily. Reorder PSI Chemistry Controls Cat.# C7590-50 & C7591-50.

Rev. 1-03

Application Code 191

Pointe Scientific, Inc.

Instrument Application

Analyzer: Hitachi 902

Test: Uric Acid

No 1. Test Name	UA
No 2. Assay Code (Mthd)	2 Point End
No 3. Assay Code (2.Test)	0
No 4. Reaction Time	10
No 5. Assay Point 1	17
No 6. Assay Point 2	20
No 7. Assay Point 3	0
No 8. Assay Point 4	0
No 9. Wavelength (SUB)	700
No 10. Wavelength (MAIN)	546
No 11. Sample Volume	7.0
No 12. R1 Volume	250
No 13. R1 Position	0*
No 14. R1 Bottle Size	Large
No 15. R2 Volume	0
No 16. R2 Position	0
No 17. R2 Bottle Size	Small
No 18. R3 Volume	50
No 19. R3 Position	0*
No 20. R3 Bottle Size	Small
No 21. Calib. Type (Type)	Linear
No 22. Calib. Type (Wght)	0
No 23. Calib. Conc. 1	0.0
No 24. Calib. Pos. 1	36
No 25. Calib. Conc. 2	0*
No 26. Calib. Pos. 2	37
No 27. Calib. Conc. 3	0
No 28. Calib. Pos. 3	0
No 29. Calib. Conc. 4	0
No 30. Calib. Pos. 4	0
No 31. Calib. Conc. 5	0
No 32. Calib. Pos. 5	0
No 33. Calib. Conc. 6	0
No 34. Calib. Pos. 6	0
No 35. S1 ABS.	0
No 36. K Factor	10000
No 37. K2 Factor	10000
No 38. K3 Factor	10000
No 39. K4 Factor	10000
No 40. K5 Factor	10000
No 41. A Factor	0
No 42. B Factor	0
No 43. C Factor	0
No 44. SD Limit	0.1
No 45. Duplicate Limit	100
No 46. Sens. Limit	700
No 47. S1ABS. Limit (L)	0
No 48. S1ABS. Limit (H)	4000
No 49. ABS Limit	0
No 50. ABS Limit (D/I)	Increase
No 51. Prozone Limit	0
No 52. Proz Limit (Upp/Low)	Lower**
No 53. Prozone (End Point)	35
No 54. Expect. Value (L)	2.4
No 55. Expect. Value (H)	7.0
No 56. Instr. Factor (a)	1.0
No 57. Instr. Factor (b)	0.0
No 58. Key Setting	-

*User-defined,

**Chemistry Parameters report will list D for lower or U for upper

It is recommended that two levels of control material be assayed daily. Reorder PSI Chemistry Controls Cat.# C7590-50 & C7591-50.

Rev. 1-03

Application Code 196